

## Profile/Photo Observation Report



|              |                   |             |                     |            |                        |
|--------------|-------------------|-------------|---------------------|------------|------------------------|
| Date:        | <b>04/14/2018</b> | Weather:    |                     | Coding:    | <b>PACP 6.0</b>        |
| Pipe Length: | <b>145.80</b>     | Owner:      | <b>NA</b>           | Pre Clean: | <b>No Pre-Cleaning</b> |
| P.O.#:       |                   | Surveyor:   | <b>Jen Costello</b> | PSR:       | <b>P-505-085-086</b>   |
| Customer:    |                   | Clean Date: | <b>01/01/1900</b>   | Shape:     | <b>C</b>               |

|             |                           |               |                       |
|-------------|---------------------------|---------------|-----------------------|
| Street:     | <b>W 4TH PL</b>           | Flow Control: | <b>Not Controlled</b> |
| City:       | <b>Hobart, IN</b>         | Year Renewed: |                       |
| Location:   | <b>Yard</b>               | Tape/Media #: |                       |
| Purpose:    | <b>Routine Assessment</b> | Dia/Height:   | <b>10"</b>            |
| Use:        | <b>Sanitary</b>           | Material:     | <b>VCP</b>            |
| Drain Area: | <b>NA</b>                 | Lining:       |                       |
| Category:   | <b>NA</b>                 |               |                       |
| Comment:    |                           |               |                       |

|                   |                  |                        |                  |
|-------------------|------------------|------------------------|------------------|
| Location Details: |                  | Direction of Survey:   | <b>Upstream</b>  |
| US MH:            | <b>M-505-085</b> | DS MH:                 | <b>M-505-086</b> |
|                   |                  | Total Length Surveyed: | <b>0.00</b>      |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <b>0.00</b> | O&M Quick:        | <b>0000</b> | O&M Rating:        | <b>0.00</b> |
| Structural Index: | <b>0.00</b> | Structural Quick: | <b>0000</b> | Structural Rating: | <b>0.00</b> |
| Overall Index:    | <b>0.00</b> | Overall Quick:    | <b>0000</b> | Overall Rating:    | <b>0.00</b> |