
Profile/Photo Observation Report						
Date:	04/22/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)	: 135.2	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Mark Ru	ıby	PSR:	P-604-085-086
Customer:		Clean Date	e: 01/01/1	900	Shape:	С
Street: ALLEY BETWEEN N WISCONSIN ST &		Flow Cont	rol:	Not Controlled		
City:	Hobart, IN		Year Rene	ewed:		
Location:	Light Highway		Tape/Mee	dia #:		
Purpose:	Not Known		Dia/Heigh	it:	12"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details	5:		Direction	of Survey:	Downstream	
US MH:	M-604-085	DS MH:	M-604-086	٦	Fotal Length Surveyed (ft)	: 133.3
O&M Index:	0.00	O&M Quicl	<:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural (0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Qui	ck:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-085



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	AMH Manhole
Distance (ft):	133.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-086