Profile/Photo Observation Report



Profile/Photo Observation Report							
Date: Pipe Length (1 P.O.#: Customer:	05/03/2018 ft): 172 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hobart M. Pielacha	Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning P-604-124-013 C		
Street:	West Old Ridge	Clean Bate.	Flow Control:	Not Controlled			
City:	Hobart, IN		Year Renewed:	Not Controlled			
Location:	Light Highway		Tape/Media #:	DEP 172			
Purpose:	Routine Assessment	t	Dia/Height:	8"			
Use:	Sanitary		Material:	PVC			
Drain Area:			Lining:				
Category:	NA						
Comment:	5-21-2018						
Location Deta	ails:		Direction of Survey	y: Downstream			
US MH:	M-604-124	DS MH:	M-604-013	Total Length Surveyed (ft)	9.7		
O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00		
Structural Inde	x: 0.00	Structural Qui	ck: 0000	Structural Rating:	0.00		
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00		

Thursday, May 4, 2023

Positio	n Code	Observation	Video (sec)	Grade
M(604) 124				
.0	AMH	Manhole	0	NA
0.	MWL	Water Level	8	NA
9.7	ATC	Tee Connection	58	NA
M 604-013				

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-604-124	

 AMH

Thursday, May 4, 2023 2



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:


Clock To: 1st Value: 2nd Value: Value Percen

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: ATC

Description: Tee Connection

Distance (ft): 9.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 6

Clock To:

1st Value: **8.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-604-013

Thursday, May 4, 2023 3