Profile/Photo Observation Report



Date: 04/15/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 174.6 Owner: NA Pre Clean: **Not Known** P.O.#: **Mark Ruby** PSR: P-703-024-023 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: PHEASANT RUN DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-703-023 DS MH: M-703-024 Total Length Surveyed (ft): 180.8

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

.0 AMH Manhole 10 .0 MWL Water Level 21 .86.6 TF Tap Factory 206 .88.7 TF Tap Factory 380 .165.3 TF Tap Factory 399 .180.8 AMH Manhole 442	Positio	n Code	Observation	Video (sec)	Grade
.0 AMH Manhole 10 .0 MWL Water Level 21 86.6 TF Tap Factory 206 88.7 TF Tap Factory 222 161.6 TF Tap Factory 380 165.3 TF Tap Factory 399	03-023				
86.6 TF Tap Factory 206 88.7 TF Tap Factory 222 161.6 TF Tap Factory 380 165.3 TF Tap Factory 399		AMH	Manhole	10	NA
88.7 TF Tap Factory 222 161.6 TF Tap Factory 380 165.3 TF Tap Factory 399	0.	MWL	Water Level	21	NA
161.6 TF Tap Factory 380 165.3 TF Tap Factory 399	86.6	TF	Tap Factory	206	NA
165.3 TF Tap Factory 399	88.7	TF	Tap Factory	222	NA
	161.6	TF	Tap Factory	380	NA
180.8 AMH Manhole 442	165.3	TF	Tap Factory	399	NA
	180.8	AMH	Manhole	442	NA

Code:



Description:	Manhole
Distance (ft).	0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-703-023

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO



Code: TF

Description: **Tap Factory**


Distance (ft): 86.6 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF**

Description: Tap Factory


Distance (ft): 88.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 8

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory


Distance (ft): 161.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 8

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

4.000

Distance (ft): 165.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 4

Clock To:

1st Value:

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: AMH
Description: Manhole



Distance (ft): 180.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-703-024