Profile/Photo Observation Report



Date: 04/15/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 362.1 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-707-039-040 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: STATE ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: heavy silt at 2'.

Location Details: Direction of Survey: **Downstream**

US MH: M-707-040 DS MH: M-707-039 Total Length Surveyed (ft): **3.4**

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
n (707- 040				
.0	AMH	Manhole	10	NA
0.0	MWL	Water Level	21	NA
3.4	MSA	Abandoned Survey	39	NA

Code:



Description:	Manhole	
	_	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-707-040	

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000

Code: MSA

Description: **Abandoned Survey**



Distance (ft): 3.4 Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: camera stopped

NO