## **Profile/Photo Observation Report**



Date: Pipe Length:	04/16/2018	Weather: Owner:	City of Ho	hart	Coding: Pre Clean:	PACP 6.0 No Pre-Cleaning
P.O.#:	65-1	Surveyor:	M. Pielac		PSR:	M-708-023-M-708-014
Customer:	City of Hobart	Clean Date:			Shape:	С
Street:	Off Lake Park Avenue	<b>!</b>	Flow Contr	ol:	Not Controlled	I
City:	Hobart, IN		Year Renev	ved:		
Location:	Parking Lot		Tape/Media #:		<b>DEP 65</b>	
Purpose:	<b>Routine Assessment</b>		Dia/Height	:	15"	
Use:	Sanitary		Material:		PVC	
Drain Area:			Lining:			
Category:	NA					
Comment:						
Location Detai	ls:		Direction o	f Survey:	Downstream	
US MH:	M-708-023	DS MH:	M-708-014		Total Length Surveyed:	0.00
D&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
Structural Index	0.00	– Structural Qu		0000	 Structural Rating:	0.00
Overall Index:	0.00	Overall Quicl		0000	Overall Rating:	0.00

Thursday, May 4, 2023 1