Profile/Photo Observation Report



Date: 04/03/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 126.4 Owner: NA Pre Clean: **Not Known** P.O.#: P-708-111-110 Jen Costello PSR: Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: BRACKEN PKWY & LINCOLN ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Sidewalk Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA
Comment: Reverse setup.

Location Details: Direction of Survey: **Downstream**

US MH: M-708-111 DS MH: M-708-110 Total Length Surveyed (ft): 133.9

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

| Position | Code | Observation | Video (sec) | Grade |
|------------|------|-------------|-------------|-------|
| M(708-)111 | | | | |
| .0 | АМН | Manhole | 11 | NA |
| 0. | MWL | Water Level | 22 | NA |
| 133.9 | AMH | Manhole | 301 | NA |
| M(708)110 | | | | |

Code:



| Description: | Manhole | |
|---------------------|-----------|--|
| D: (1) | | |
| Distance (ft): | .0 | |
| Structural Grade: | 0 | |
| O&M Grade: | 0 | |
| Clock Start/From: | | |
| Clock To: | | |
| 1st Value: | | |
| 2nd Value: | | |
| Value Percent: | | |
| Continuous Index: | | |
| Within 8" of Joint: | NO | |
| Remarks: | M-708-111 | |
| | | |

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value:

2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint:

NO

30.000

Remarks:

Code: AMH Description: Manhole

Distance (ft): 133.9 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-708-110