

Profile/Photo Observation Report



Date:	04/13/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	220.0	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-803-041-042
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	510 Indiana St	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Easement/Right of Way	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	15"
Use:	Sanitary	Material:	VCP
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	411-1		
Location Details:	Flows through easement	Direction of Survey:	Upstream
US MH:	M-803-041	DS MH:	M-803-042
		Total Length Surveyed (ft):	220.0

O&M Index:	2.92	O&M Quick:	3A21	O&M Rating:	35.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	2.92	Overall Quick:	3A21	Overall Rating:	35.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	16	NA
	.0	MWL	Water Level	33	NA
	79.2	TF	Tap Factory	249	NA
	135.7	TF	Tap Factory	406	NA
	163.5	RMJ(S01)	Roots Medium Joint	532	M 3
	175.4	TFD	Tap Factory Defective	574	M 2
	219.5	RMJ(F01)	Roots Medium Joint	679	M 3
	220.0	AMH	Manhole	729	NA



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-042



Code: **MWL**
 Description: **Water Level**

Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **TF**
 Description: **Tap Factory**

Distance (ft): **79.2**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From: **10**
 Clock To:
 1st Value: **6.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **TF**
 Description: **Tap Factory**

Distance (ft): **135.7**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From: **2**
 Clock To:
 1st Value: **6.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **RMJ**
 Description: **Roots Medium Joint**

Distance (ft): **163.5**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **4**
 Clock To: **8**
 1st Value:
 2nd Value:
 Value Percent: **10.000**
 Continuous Index: **S01**
 Within 8" of Joint: **YES**
 Remarks:



Code: **TFD**
 Description: **Tap Factory Defective**

Distance (ft): **175.4**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **11**
 Clock To:
 1st Value: **4.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **Defective**



Code: **RMJ**
 Description: **Roots Medium Joint**

Distance (ft): **219.5**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **4**
 Clock To: **8**
 1st Value:
 2nd Value:
 Value Percent: **10.000**
 Continuous Index: **F01**
 Within 8" of Joint: **YES**
 Remarks:



Code:	AMH
Description:	Manhole
Distance (ft):	220.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-041