

Profile/Photo Observation Report



Date:	04/18/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	220.5	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-803-046-052
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	High St	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Light Highway	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	15"
Use:	Sanitary	Material:	VCP
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	413-5		
Location Details:	Edge of street	Direction of Survey:	Downstream
US MH:	M-803-046	DS MH:	M-803-052
		Total Length Surveyed (ft):	220.5

O&M Index:	1.00	O&M Quick:	1G00	O&M Rating:	40.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	1.00	Overall Quick:	1G00	Overall Rating:	40.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	14	NA
	.0	MWL	Water Level	29	NA
	19.6	RFJ(S01)	Roots Fine Joint	109	M 1
	114.5	MWL	Water Level	240	NA
	127.0	TF	Tap Factory	268	NA
	220.5	RFJ(F01)	Roots Fine Joint	438	M 1
	220.5	AMH	Manhole	498	NA



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-046



Code: **MWL**
 Description: **Water Level**

Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **10.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **RFJ**
 Description: **Roots Fine Joint**

Distance (ft): **19.6**
 Structural Grade: **0**
 O&M Grade: **1**
 Clock Start/From: **11**
 Clock To: **3**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index: **S01**
 Within 8" of Joint: **YES**
 Remarks: **wanders**



Code: **MWL**
 Description: **Water Level**

Distance (ft): **114.5**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **TF**
 Description: **Tap Factory**

Distance (ft): **127.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From: **1**
 Clock To:
 1st Value: **6.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	220.5
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	11
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	wanders



Code:	AMH
Description:	Manhole
Distance (ft):	220.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-052