## **Profile/Photo Observation Report**



Date: 03/26/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 128.0 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-803-028-055 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N LIBERTY CT Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-803-055 DS MH: M-803-028 Total Length Surveyed (ft): 122.4

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

803-055				Grade
.0	AMH	Manhole	10	NA
.0	MWL	Water Level	21	NA
75.9	TF	Tap Factory	185	NA
98.7	TF	Tap Factory	242	NA
122.4	AMH	Manhole	302	NA

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-803-055	

 $\mathsf{AMH}$ 



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:


Clock To:
1st Value:
2nd Value:
Value Person

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TF
Description: Tap Factory

Distance (ft): 75.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2
Clock To:

1st Value: 2nd Value: Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

YES

4.000



Code: **TF** 

Description: Tap Factory

Distance (ft): 98.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 122.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-803-028