


Profile/Photo Observation Report



Date:	04/24/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	79.0	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-803-064-LS024
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	37th Ave	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Parking Lot	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	6"
Use:	Sanitary	Material:	PVC
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	430-1. DSMH incorrect in video overlay.		
Location Details:	Quik Lube parking lot	Direction of Survey:	Downstream
US MH:	M-803-064	DS MH:	LS024
		Total Length Surveyed (ft):	79.0

O&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Quick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick:	0000	Overall Rating:	0.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	20	NA
	.0	MWL	Water Level	34	NA
	79.0	AWW	Wet Well	1303	NA



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-064



Code:	MWL
Description:	Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AWW
Description:	Wet Well
Distance (ft):	79.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-803-LS015