Profile/Photo Observation Report



Date: 04/09/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 294.1 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-804-021-020

Customer: Clean Date: 01/01/1900 Shape: C

Street: E Hickey St. Alley Flow Control: Not Controlled
City: Hobart, IN Year Renewed:

Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 8"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-804-021 DS MH: M-804-020 Total Length Surveyed (ft): 4.6

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:

	Position	Code	Observation	Video (sec)	Grade
M(804-)0	20				
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
- 11	\\.0	DAGS	Deposits Attached Grease	32	M 2
-11	2.5	TFC	Tap Factory Capped	48	NA
-11	4.6	MSA	Abandoned Survey	63	NA
Camera Direction					

Code:



Description:	Manhole
Distance (ft): Structural Grade:	.0 0
O&M Grade: Clock Start/From:	0
Clock To: 1st Value:	
2nd Value: Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-804-020

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code:

DAGS

Description: Deposits Attached Grease



Distance (ft): .0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TFC

Description: Tap Factory Capped

Distance (ft): 2.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 4.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: unknown