Profile/Photo Observation Report

0.00

Overall Quick:

Overall Index:



0.00

Data	04/20/2019	\Mootho:		Coding	ROBOTIC
Date:	04/30/2018	Weather:	City, of Habant	Coding:	PACP 6.0
Pipe Length (ft)		Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	141	Surveyor:	M. Pielacha	PSR:	P-805-051-052
Customer:	City of Hobart	Clean Date:		Shape:	С
Street:	Linda Street		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:	DEP 141	
Purpose:	Routine Assessment		Dia/Height:	15"	
Use:	Sanitary		Material:	VCP	
Drain Area:			Lining:		
Category:	NA				
Comment:	5-21-2018				
Location Details:			Direction of Surve	y: Downstream	
US MH:	M-805-052	DS MH:	M-805-051	Total Length Surveyed (fi	t): 122.4
D&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
tructural Index:	0.00	— Structural Qı	uick: 0000	Structural Rating	. 0.00


0000

Overall Rating:

Thursday, May 4, 2023

Position	Code	Observation	Video (sec)	Grade
805-052				
.0	AMH	Manhole	0	NA
0.	MWL	Water Level	8	NA
34.9	TF	Tap Factory	199	NA
65.7	TF	Tap Factory	246	NA
71.3	ТВ	Tap Break-in	262	NA
96.2	TFC	Tap Factory Capped	422	NA
122.4	AMH	Manhole	478	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-805-052

AMH

Thursday, May 4, 2023 2



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock Start/From Clock To:

1st Value: 2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 34.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **5.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

Thursday, May 4, 2023 3



Code: TF

Description: **Tap Factory**

Distance (ft): 65.7 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 3

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



TB Code:

Description: Tap Break-in

Distance (ft): 71.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:


4.000 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

Thursday, May 4, 2023



Code: TFC

Description: Tap Factory Capped

Distance (ft): 96.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:


1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: AMH
Description: Manhole

Distance (ft): 122.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-805-051

Thursday, May 4, 2023 5