
Date:	<b>10/22/2021</b>	Weather: Owner:	Hobart, IN	Coding: Pre Clean:	PACP 6.0 Not Known
Pipe Length (ft P.O.#:	967_1	Surveyor:	M. Pielacha	Pre Clean. PSR:	P-806-041-042
Customer:	Hobart, IN	Clean Date:		Shape:	C
Street:	Off 10th Street		Flow Control:		
City:	Hobart, IN		Year Renewed:		
Location:	Sidewalk		Tape/Media #:	967	
Purpose:	<b>Routine Assessment</b>		Dia/Height:	8"	
Use:	Sanitary		Material:	PVC	
Drain Area:			Lining:		
Category:	NA				
Comment:					
Location Detail	ls:		Direction of Surve	y: Upstream	
US MH:	M-806-41	DS MH:	M-806-42	Total Length Surveyed (ft)	193.5
0&M Index:	0.00	O&M Quick:	0000	O&M Rating:	0.00
Structural Index:	0.00		uick: 0000	Structural Rating:	0.00
Overall Index:	0.00	 Overall Quick		Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-806-42

Thursday, May 4, 2023



Code:	MWL
Description:	Water Level
	•
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



F ap Factory
6.8
)
)
.000
10



Code: Description:	AMH Manhole
Distance (ft):	193.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-806-41