Profile/Photo Observation Report



Date: 04/15/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 188.8 Owner: NA Pre Clean: **Not Known** P.O.#: P-907-004-012 PSR: Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: Capitol Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: battery at 257'. longer than mapped

Location Details: Direction of Survey: Upstream

US MH: M-807-012 DS MH: M-907-004 Total Length Surveyed (ft): 258.8

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

	Observation	Video (sec)	Grade
AMH	Manhole	10	NA
MWL	Water Level	21	NA
.9 TF	Tap Factory	150	NA
4.1 TFC	Tap Factory Capped	298	NA
7.0 TF	Tap Factory	419	NA
8.8 AMH	Manhole	596	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-907-004

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.0

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

4.000

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 57.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

1st Value: 2nd Value:

Clock To:

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TFC**

Description: Tap Factory Capped

Distance (ft): 124.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory


Distance (ft): 177.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 258.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To: 1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-807-012