


Profile/Ph	oto Observatio	n Report				RedZon
Date:	03/22/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 401.9	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	JUSTIN GOI	NZALES	PSR:	P-808-016-014
Customer:		Clean Date:	01/01/1900)	Shape:	C
Street:	INDEPENDENCE DR & LIBERTY ST		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewe	d:		
Location:	Light Highway		Tape/Media	#:		
Purpose:	Maintenance Rela	ated	Dia/Height:		8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	ls:		Direction of S	Survey:	Upstream	
US MH:	M-808-014	DS MH:	M-808-016	То	tal Length Surveyed (ft)	: 393.1
&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
tructural Index:	0.00	Structural Q	uick:	0000	Structural Rating:	0.00
Verall Index:	0.00	Overall Quic	k:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-808-016		



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code:	AMH	
Description:	Manhole	
	202.4	
Distance (ft):	393.1	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-808-014	