
Date:	03/21/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft):	24.4	Owner:	NA	Pre Clean:	Not Known
P.O.#:	24.4	Surveyor:	Selasie Honu	PSR:	P-902-048-059
Customer:		Clean Date:		Shape:	C
Street:	RUSH PL		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Details:			Direction of Surve	y: Upstream	
US MH: N	M-902-059	DS MH:	M-902-048	Total Length Surveyed (ft)	: <b>3.3</b>
D&M Index:	1.00	O&M Quick:	1100	O&M Rating:	1.00
Structural Index:	0.00	Structural Qu	uick: 0000	Structural Rating:	0.00
Overall Index:	1.00	Overall Quicl			1.00




AMH Manhole
.0
0
0
NO
M-902-048



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	LLD Alignment Left Down
Distance (ft):	2.0
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code: Description: MSA Abandoned Survey



Distance (ft):	3.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	bend