
Profile/Ph	oto Observatio	n Report			RedZone
Date:	03/30/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)): 59.4	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-903-048-023
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	ALLEY BETWEEN	EY BETWEEN RUSH ST & BRANDT Flow Control:		Not Controlled	ł
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	10"	
Use:	Sanitary		Material:	PVC	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detail	S:		Direction of Sur	vey: Upstream	
US MH:	M-903-023	DS MH:	M-903-048	Total Length Surveyed (ft): 54.5
0&M Index:	0.00	O&M Quick:	000	00 O&M Rating:	0.00
itructural Index:	0.00	Structural Qu	uick: 000	00 Structural Rating	0.00
Overall Index:	0.00	Overall Quicl	<: 000	00 Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-903-048



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



AMH Manhole
54.5
0
0
NO
M-903-023