Profile/Photo Observation Report



Date: 05/04/2018 Weather: **PACP 4.2** Coding: Pipe Length (ft): Owner: **City of Hobart** Pre Clean: No Pre-Cleaning 31.8 P.O.#: 2004 PSR: P-904-006-007 Surveyor: SAN Customer: **Red Zone** Clean Date: Shape: 2326 Pembroke Dr Flow Control: **Not Controlled** Street: City: **Hobart In** Year Renewed: Easement/Right of Way Tape/Media #: Deliverable 1 Location: Purpose: **Routine Assessment** Dia/Height: 18" **PVC** Use: Sanitary Material: Northeast Drain Area: Lining: NA Category: Comment: 448-4 **Location Details:** Edge of field Direction of Survey: Upstream M-904-006 US MH: DS MH: M-904-007 Total Length Surveyed (ft): 31.8

0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

Thursday, May 4, 2023

Position	Code	Observation	Video (sec)	Grade
904-007				
.0	AMH	Manhole	9	NA
0.	MWL	Water Level	30	NA
31.8	AMH	Manhole	222	NA
904)006				



C	Code:	AMH
	Description:	Manhole
_	Nistanas (ft).	0
L	Distance (ft):	.0
S	tructural Grade:	0
C	0&M Grade:	0
C	Clock Start/From:	
C	Clock To:	
1	st Value:	
2	Ind Value:	
٧	/alue Percent:	
C	Continuous Index:	
٧	Vithin 8" of Joint:	NO
R	Remarks:	M-904-007

Thursday, May 4, 2023 2



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 31.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-904-006

Thursday, May 4, 2023 3