## **Profile/Photo Observation Report**

0.00

0.00

Structural Quick:

Overall Quick:

Structural Index:

Overall Index:



0.00

0.00

Date: 05/04/2018 Weather: **PACP 4.2** Coding: Pipe Length (ft): 244.8 Owner: **City of Hobart** Pre Clean: No Pre-Cleaning P.O.#: 2004 PSR: P-904-007-071 Surveyor: SAN **Red Zone** Customer: Clean Date: Shape: 2318 N Pembroke Dr Flow Control: **Not Controlled** Street: City: **Hobart In** Year Renewed: Easement/Right of Way Tape/Media #: Deliverable 1 Location: Purpose: **Routine Assessment** Dia/Height: 18" **PVC** Use: Sanitary Material: Northeast Drain Area: Lining: NA Category: Comment: 448-3 **Location Details:** Edge of field Direction of Survey: Upstream M-904-007 US MH: DS MH: M-904-071 Total Length Surveyed (ft): 244.8 0.00 0000 0.00 O&M Index: O&M Quick: O&M Rating:

0000

0000


Structural Rating:

Overall Rating:

Thursday, May 4, 2023 1

Positio	n Code	Observation	Video (sec)	Grade
л <del>(</del> 904 <del>)</del> 071				
.0	AMH	Manhole	15	NA
0.	MWL	Water Level	60	NA
244.8	AMH	Manhole	484	NA
n(-904)007				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:  O&M Grade:	0 0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-904-071

AMH

Thursday, May 4, 2023 2



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

25.000



Code: AMH Description: Manhole

Distance (ft): 244.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks: M-904-007

3 Thursday, May 4, 2023