

Profile/Photo Observation Report



Date:	04/21/2018	Weather:		Coding:	PACP 4.2
Pipe Length (ft):	170.3	Owner:	City of Hobart	Pre Clean:	No Pre-Cleaning
P.O.#:	2004	Surveyor:	SAN	PSR:	P-904-047-051
Customer:	Red Zone	Clean Date:		Shape:	C

Street:	1705 Hickey St	Flow Control:	Not Controlled
City:	Hobart In	Year Renewed:	
Location:	Woods	Tape/Media #:	Deliverable 1
Purpose:	Routine Assessment	Dia/Height:	18"
Use:	Sanitary	Material:	VCP
Drain Area:	Northeast	Lining:	
Category:	NA		
Comment:	425-2/Incomplete due to debris/ Line needs to be cleaned 62 feet from MH 047.		
Location Details:	Flows from yard to woods	Direction of Survey:	Downstream
US MH:	M-904-047	DS MH:	M-904-051
		Total Length Surveyed (ft):	62.0

O&M Index:	3.00	O&M Quick:	3200	O&M Rating:	6.00
Structural Index:	3.00	Structural Quick:	3100	Structural Rating:	3.00
Overall Index:	3.00	Overall Quick:	3300	Overall Rating:	9.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	242	NA
	.0	MWL	Water Level	260	NA
	.0	MGO	General Observation	284	NA
	30.3	MGO	General Observation	20	NA
	30.3	RMJ	Roots Medium Joint	384	M 3
	46.2	MWLS	Water Level Sag	61	S 3
	62.0	MSA	Abandoned Survey	16	NA



Code:	AMH
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-904-047



Code: **MWL**
 Description: **Water Level**

Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **15.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **MGO**
 Description: **General Observation**

Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **infil in manhole**



Code:	MGO
Description:	General Observation
Distance (ft):	30.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	resume after down sizing



Code:	RMJ
Description:	Roots Medium Joint
Distance (ft):	30.3
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	MWLS
Description:	Water Level Sag
Distance (ft):	46.2
Structural Grade:	3
O&M Grade:	3
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	35.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MSA
Description:	Abandoned Survey
Distance (ft):	62.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	line needs cleaned