Profile/Photo Observation Report



P-904-061-060

Date: 04/05/2018 Weather: Coding: **PACP 6.0** Pipe Length (ft): 329.6 Owner: NA Pre Clean: **Not Known** P.O.#:

Jen Costello

PSR:

Customer: 01/01/1900 Clean Date: Shape:

DIVISION ST & RUSH CT Flow Control: **Not Controlled** Street:

Surveyor:

City: Hobart, IN Year Renewed: Other Tape/Media #: Location:

Purpose: **Not Known** Dia/Height: 10" Use: Sanitary Material: **VCP**

NA Lining: Drain Area:

NA Category:

Comment:

Location Details: Direction of Survey: Upstream

US MH: M-904-060 Total Length Surveyed (ft): M-904-061 DS MH: 36.4

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Index: Structural Quick: Structural Rating: 0.00 0000 0.00 Overall Index: Overall Rating: Overall Quick:

_	Code	Observation	Video (sec)	Grade
904-060				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
25.3	TFA	Tap Factory Active	84	NA
36.4	MSA	Abandoned Survey	117	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-904-060

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

20.000

Code: **TFA** Description:

Tap Factory Active



Distance (ft): 25.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9

Clock To:

Remarks:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: MSA

Description: Abandoned Survey

Distance (ft): 36.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: UNKNOWN