

| Profile/Ph        | oto Observatio   | n Report       |                   |                            | RedZon<br>R 0 B 0 T I C S |
|-------------------|------------------|----------------|-------------------|----------------------------|---------------------------|
| Date:             | 04/15/2018       | Weather:       |                   | Coding:                    | PACP 6.0                  |
| Pipe Length (ft   | ): <b>258.6</b>  | Owner:         | NA                | Pre Clean:                 | Not Known                 |
| P.O.#:            |                  | Surveyor:      | Selasie Honu      | PSR:                       | P-907-003-004             |
| Customer:         |                  | Clean Date:    | 01/01/1900        | Shape:                     | С                         |
| Street:           | S HOBART RD      |                | Flow Control:     | Not Controlled             |                           |
| City:             | Hobart, IN       |                | Year Renewed:     |                            |                           |
| Location:         | Light Highway    |                | Tape/Media #:     |                            |                           |
| Purpose:          | Maintenance Rela | ated           | Dia/Height:       | 12"                        |                           |
| Use:              | Sanitary         |                | Material:         | PVC                        |                           |
| Drain Area:       | NA               |                | Lining:           | Cured in Place             |                           |
| Category:         | NA               |                |                   |                            |                           |
| Comment:          | mh found, shorte | r than mapped. |                   |                            |                           |
| Location Detai    | ls:              |                | Direction of Surv | ey: Downstream             |                           |
| US MH:            | M-907-004        | DS MH:         | M-907-003         | Total Length Surveyed (ft) | : <b>202.0</b>            |
| D&M Index:        | 0.00             | O&M Quick:     | 000               | 0 O&M Rating:              | 0.00                      |
| Structural Index: | 0.00             | Structural Q   | uick: 000         | 0 Structural Rating:       | 0.00                      |
| Overall Index:    | 0.00             | Overall Quic   | k: 000            | <b>0</b> Overall Rating:   | 0.00                      |





| Code:<br>Description: | AMH<br>Manhole |
|-----------------------|----------------|
| Distance (ft):        | .0             |
| Structural Grade:     | 0              |
| O&M Grade:            | 0              |
| Clock Start/From:     |                |
| Clock To:             |                |
| 1st Value:            |                |
| 2nd Value:            |                |
| Value Percent:        |                |
| Continuous Index:     |                |
| Within 8" of Joint:   | NO             |
| Remarks:              | M-907-004      |



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:




| TF<br>Tap Factory |
|-------------------|
| 99.4              |
| 0                 |
| 0                 |
| 2                 |
|                   |
| 4.000             |
|                   |
|                   |
|                   |
|                   |
|                   |
|                   |



| Code:             | TF          |
|-------------------|-------------|
| Description:      | Tap Factory |
|                   |             |
| Distance (ft):    | 165.3       |
| ( )               |             |
| Structural Grade: | 0           |
| O&M Grade:        | 0           |
| Clock Start/From: | 2           |
| Clock To:         |             |
| 4 -+ 1 / - 1      | 4 000       |

1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:

4.000



| Code:               | TF          |
|---------------------|-------------|
| Description:        | Tap Factory |
|                     |             |
| Distance (ft):      | 167.2       |
| Structural Grade:   | 0           |
| O&M Grade:          | 0           |
| Clock Start/From:   | 10          |
| Clock To:           |             |
| 1st Value:          | 4.000       |
| 2nd Value:          |             |
| Value Percent:      |             |
| Continuous Index:   |             |
| Within 8" of Joint: |             |
| Remarks:            |             |
|                     |             |



Code:AMHDescription:Manhole

| Distance (ft):      | 202.0     |
|---------------------|-----------|
| Structural Grade:   | 0         |
| O&M Grade:          | 0         |
| Clock Start/From:   |           |
| Clock To:           |           |
| 1st Value:          |           |
| 2nd Value:          |           |
| Value Percent:      |           |
| Continuous Index:   |           |
| Within 8" of Joint: | NO        |
| Remarks:            | M-907-003 |
|                     |           |