Profile/Photo Observation Report



Date: 03/28/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 172.1 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: Selasie Honu PSR: P-910-028-018

Customer: Clean Date: 01/01/1900 Shape: C

Street: OFF NORRIS DR Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Ditch Tape/Media #:

Purpose: Maintenance Related Dia/Height: 8"
Use: Sanitary Material: PVC

Drain Area: **NA** Lining:

Category: NA
Comment: Flow direction wrong. Redeployment.


Location Details: Direction of Survey: Upstream

US MH: M-910-018 DS MH: M-910-028 Total Length Surveyed (ft): 28.3

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:


Position	Code	Observation	Video (sec)	Grade
028				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
28.3	MSA	Abandoned Survey	89	NA

Code:



Description:	Manhole
/**	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-910-028

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000



Code: MSA

Description: **Abandoned Survey**

Distance (ft): 28.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped